








Your Instructor For This Webinar

"G" Jerry Truglia

- National Trainer, ASE World Class, Master Auto, Truck, School Bus, L1, L3, CNG and...
- ATTP Master Instructor, New York State, CT and New Jersey
- STS (Service Technician Society) 2003 President
- TST (Technicians Service Training) Founder and President
- Author / Co Author/ Technical adviser on 25 plus books including OBD II and Mode 6, and Understanding and Diagnosing Hybrid Vehicles
- Published articles for multiple newsletters, and magazines
- Picked as one of the Top Instructors in the country by EPA & SAE
- Numerous Radio, TV, Internet, and SAE Video appearances
- PTEN, MotorAge and TST Webcast Instructor
- Motor Magazine Top 20 award winner
- Provider of OBD II Training for 14 states, Ontario Canada and the US EPA
- Guest speaker at SAE Congress, IM Solutions and Clean Air Conference

O DORMAN







6.7 L PowerStroke - 4 Generations Of Ford's Diesel Powerplant

· DORMAN








Gen 1 Model Year Changes


2012


- A stamped steel oil pan with a conventional bolt-type oil plug replaced the plastic oil pan and plastic 1/4 turn drain valve.
- Revised oil cooler secures without any hidden hardware; to remove original oil cooler, the lower oil pan needed to be removed in order to access a hidden stud securing the oil cooler assembly from the back side. Revised oil cooler is secured with exterior bolts only and is serviceable without removing the lower oil pan.
- DPF differential pressure sensor added to exhaust system to measure the pressure differential across the diesel particulate filter for the purpose of monitoring DPF condition.


· TORMANT

• Revised oil and coolant feed lines for the turbocharger, quick connect fittings replaced with conventional bolt on fittings for improved sealing and durability.











The cooling and lube lines going to the turbocharger have been changed from quick connections, to bolt type. This update is more durable preventing leaks due to better sealing ability.

C DORMAN

13







The Hall Effect crankcase ventilation sensor is mounted on a hose that is connected by a tamper proof connector at the air intake hose.

First used in 2013 Super Duty

· DORMAN

Gen 2: 2015 - 2019 Courtesy of Ford Motor Company C DORMAN 16






Gen 2 Model Year Changes

2015

- Temperature sensor added to the inlet of the EGR cooler (pickup trucks only).
- Revised fan clutch design with additional heat sinks in order to more effectively dissipate heat, thereby improving durability.
- IROX polymer coated lower main bearings introduced for added durability at greater performance levels.
- Larger GT37 single variable geometry turbocharger replaces the GT32 twin compressor "DualBoost" turbo. Improved throttle response and high altitude performance. Wastegate eliminated, turbocharger produces ~30 psi at max load with an impeller speed of ~130,000 rpm.

C DORMAN




Gen 2 Model Year Changes


2015


- Upgraded high pressure fuel pump (injection pump). New pump looks identical but features a longer stroke.
- Revised injector design, more efficiency nozzle design for reduced emissions and improved performance.
- Revised crankshaft damper design with added mass; necessary due to the increased torsional forces produced by the more powerful engine.


C DORMAN

- Revised lower main bearings with IROX polymer coating.
- Strengthened cylinder head design.
- High capacity torque converter introduced; transmission shift schedule not significantly altered.











This sensor is a thermistor sensor that operates by the electrical resistance decreases as temp increases. A voltage signal is sent to the PCM that is converted into a temperature reading.

· DORMAN



EGR Cooler



The coolant flow through the EGR has changed. The EGR cooler is a carryover from the previous years but the secondary cooling systems no longer cools the EGR gases.

The newer engines use the high temperature cooling system.

As pictured the ECT2 sensor had been removed and plugged. On 2015 and newer the plug is deleted.


O DORMAN

EGT2 Cooler Sensor


<image>

Due to the EGR Cooler flow change the ECT2 is now mounted in a fitting in the coolant line. It's located in the right front engine compartment under the air filter box.


















Maintenance Notes

C DORMAN


















<section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header>



Cooling System Service

The coolant level should always be checked during a PM (service interval) and it should also be checked with a refractometer and coolant strips.

The coolant should be an Ethylene Glycol (EG) or Propylene Glycol (PG) based antifreeze and be mixed with clear water that has a hardness of less than 300 ppm and less than 100 ppm chlorine. Also avoid are softened water because of harmful chemicals it contains.






"Dusting" A Diesel


- The integrity of the air intake plumbing is critical to preventing dirt/dust from entering the engine. This was a major problem with military vehicles in Iraq and Afghanistan.
- Dirt and debris that make it past the filter can lead to extreme damage to the turbocharger.
- To make things worse, metal from the failed turbocharger can find its way into the engine, circulating throughout the system. This can result in complete engine failure.




O DORMAN







<image><image><text><text>




VGT Turbos (The New Ones)


NOTE: VANES CAN STICK AND THE 6.7 L HAS ISSUES WITH THE ACTUATOR MECHANISM BINDING. BOTH CAN CAUSE UNDERBOOST OR OVERBOOST DTCs.


BEST PRACTICE: Allow engine to idle for a few minutes as a cool down period before shutting engine down.



O DORMAN











DEF Fluid Issues


- A leak in the reductant system can be located by inspecting for a build - up of crystallized diesel exhaust fluid.
- Dirt / metal contamination can cause abrasion of the DEF pump. Dirt, rust or tank scale can occur with improper DEF storage or handling

































































































<section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header>


Bosch CP4 Fuel Pump

The Bosch CP4 HP pump used on the 6.7L is its Achilles Heel. According to Ford, the primary cause of these failures is related to fuel quality and/or contamination. In addition, fuel quality may cause symptoms including, but not limited to, the following:

- Crank No Start
- Long Crank/Hard Start
- Runs Rough
- Low Power
- Engine Knocking
- Exhaust Smoke
- Fuel Rail Pressure (FRP) slow to build





O DORMANT













- Make sure OEM filters are used (aftermarket filters are known to suck shut under load)
- Make sure you follow proper service info to bleed out fuel system when replacing filters
- Make sure lower filter cap is installed correctly and not broken
- 2. Lower Fuel Bowl The lower filter bowl is not tightened to a torqued value; there are stopping tabs on the lower and upper housings that should contact each other when the lower bowl is fully tightened (Figure 1). If the lower bowl is over-tightened or if pneumatic tools are used for service, these tabs may break and cause O-ring damage allowing air to enter the system. If the tabs are broken, then that part of the DFCM will need to be replaced. Damage to the DFCM stopping tabs not warrantable.




Courtesy of Ford Motor Company

C DORMAN


95





No Start/Hard Start

- If there is no contamination, remove the return hose from the Pressure Control Valve in the left fuel rail. Plug the hose leading to the fuel return system. Crank the engine and watch for fuel flow from the valve. If there is a measurable amount of return, the valve is bad. If not, the valve is holding pressure.
- Check the injectors for excessive return. Remove the return line and plug the rails with a suitable tool, then crank the engine while watching the injector returns. A small amount of return is normal, but more than 3 ml in 15 seconds while cranking or at idle is considered excessive. (Ford does not specify a return specification or injector return diagnostic procedures. This is a spec for the Duramax using similar system.)









We offer greater freedom to fix cars and trucks by engineering exclusive, labor-saving and cost-effective repair solutions.

